



YZ401

MAKE:	MACLEAN
MODEL:	MEM - 946
YEAR:	2011
SERIAL NUMBER:	946-313
UNIT HOURS:	2,500
FIRE SUPPRESSION:	YES - ANSUL
ENGINE MAKE:	MERCEDES - BENZ
ENGINE MODEL:	OM904LA
TRANSMISSION MAKE:	DANA
TRANSMISSION MODEL:	3200
CONVERTER MAKE:	
CONVERTER MODEL:	
BRAKES MAKE:	
BRAKES TYPE - SERVICE:	
BRAKES TYPE - PARKING - EMERGENCY:	
AXLES MAKE:	NEW HOLLAND
AXLES MODEL:	D65
PERCUSSION:	2911 HRS.
DRILL:	SANDVIK - HYDRASTAR H200
TIRE SIZE:	12.00 - 20 - RIM - 12 BOLT - 5" INSET - 14.5" CENTER
OPEN CANOPY:	
ROPS/FOPS:	YES - S/N 375.1009901
OPEN CANOPY CONDITION:	GOOD
VOLTAGE:	575VAC / 3 PHASE / 60 HZ
POWER PACK HRS.	8999 HRS



YZC EQUIPMENT INSPECTION REPORT

UNIT YZ-401 DESCRIPTION MACLEAN 946 BOLTER HOURS 2500DATE 28/06/16....

RUNNING INFORMATION
ENGINE STARTS EASILY AND RUNS GOOD LOW IDLE 900 HIGH IDLE 2350
ENGINE OIL PRESSURE LOW IDLE 40.6 P.S.I. HIGH IDLE 64.4 P.S.I.
TURBO BOOST 35.4 P.S.I.
TRANSMISSION PRESSURE 300 P.S.I.
CHARGING VOLTAGE 27.7 VOLTS
600 VOLT WORKS GOOD NO POWER KICK OUTS, COMPRESSOR WORKS GOOD, PERCUSSION WORKS
TRANSMISSION SHIFTS GOOD AND RUNS GOOD, TWO FORWARD AND TWO REVERSE GEARS
PASSES PARK BRAKE AND SERVICE BRAKE TESTS
GENERAL INFORMATION
NO ENGINE FAULTS
ALL FOUR TIRES 90% REMAINING LIFE RIMS AND WHEEL BOLTS GOOD
REAR AXLE MOUNT BOLTS TIGHT, OSCILLATION AXLE GOOD
DRIVE LINES, SLIP JOINTS, "U" JOINTS GOOD
AXLE MOUNTED BRAKE CYLINDERS GOOD NO LEAKS
ENGINE MOUNTS GOOD, TRANSMISSION MOUNTS GOOD, RADIATOR MOUNTS GOOD
RADIATOR AND AIR TO AIR COOLER GOOD NO LEAKS , HOSING IS GOOD
STEERING CYLINDERS GOOD NO LEAKS, PINS/BUSHINGS GOOD,STOPS GOOD
ARTICULATION IS GOOD, AUTO GREASER WORKS
FRONT AND REAR JACKS GOOD, NO LEAKS
SCISSOR LIFT CYLINDERS GOOD, NO LEAKS, SCISSOR ROLLERS GOOD,SCISSOR FRAMES GOOD, NO CRACKS
ALL OPERATOR DASH SWITCHES AND GAUGES WORK, ALL DECK SWITCHES AND CONTROLS WORK
600 VOLT DECK LIGHT WORKS, BATTERIES ARE FAIR CONDITION
DECK EXTENSION CYLINDERS GOOD NO LEAKS
DRILL SLIDES GOOD, SWELLEX SLIDES GOOD,
DRILL AND SWELLEX FEED/RETURN CHAINS ARE GOOD, BOTH FEEDS WORK
DRILL WORKS, PERCUSSION WORKS ON DRILL AND SWELLEX
DRILL CROWD WORKS, BOOM CROWD WORKS , SIDE SHIFT WORKS, TILT FUNCTION WORKS

DRILL HYDRAULIC CENTRALIZER WORKS
600 VOLT WATER BOOST PUMP WORKS

COMPLETE.....

.....SIGNATURE:.....



YZC EQUIPMENT INSPECTION REPORT

UNIT YZ-401 DESCRIPTION MACLEAN 946 BOLTER HOURS 2500DATE 28/06/16....

FAILED INSPECTION INFORMATION
ENGINE OIL LEAK, OIL LINE FROM REMOVED ENGINE AIR COMPRESSOR NOT CAPPED OFF PROPERLY
ENGINE AIR COMPRESSOR HAS BEEN REMOVED
HYDRAULIC HOSE LEAK IN ARTICULATION AREA
AIR FILTER HOUSING FILTER CAP MISSING CLIPS HELD ON WITH DUCT TAPE, NEEDS NEW FILTERS
SEAT IS NO GOOD FALLING APART
NEEDS A NEW SEAT BELT
FNR SWITCH ON OPERATOR DASH IS NOT THE PROPER SWITCH, BUT IT DOES WORK
NO REAR DRIVING LIGHTS WORK, ALL ARE BROKEN
TWO FRONT LIGHTS NOT WORKING
NO STROBE LIGHT
GROUND STRAP BROKEN AT ARTICULATION FRAME JOINT
TILT INTERLOCK NOT WORKING RIGHT, NEED TO HOLD OVERRIDE BUTTON ALL THE TIME FOR FUNCTIONS
STINGER BALL WORN OUT
BOOM CROWD CYLINDER LEAKS AT ROD GUIDE
DRILL CROWD CYLINDER LEAKS AT ROD GUIDE
ONE DRIFTER MOUNT BOLT MISSING
DRILL FEED DRIVE SPROCKET SUPPORT BEARING COMING APART
SWELLEX PUMP HAS BEEN REMOVED
DECK FALL OUT WINGS BENT AND DAMAGED
SCISSOR DECK RAILINGS AND SAFETY CHAINS COULD USE SOME MINOR REPAIRS
REAR DRIVING LIGHT GAURDS PUSHED IN
PLASTIC 600 VOLT PANEL CURTAIN PROTECTOR POOR CONDITION
HYDRAULIC HOSING NEEDS SOME TIDYING UP

COMPLETE.....

.....SIGNATURE:.....



YZ402	
MAKE:	MACLEAN
MODEL:	MEM - 928
YEAR:	
SERIAL NUMBER:	928-336
UNIT HOURS:	1255 HRS.
FIRE SUPPRESSION:	YES - ANSUL
ENGINE MAKE:	MERCEDES - BENZ
ENGINE MODEL	OM904LA
TRANSMISSION MAKE:	
TRANSMISSION MODEL:	
CONVERTER MAKE:	
CONVERTER MODEL:	
BRAKES MAKE:	
BRAKES TYPE - SERVICE:	
BRAKES TYPE - PARKING - EMERGENCY:	
AXLES MAKE:	
AXLES MODEL:	
PERCUSSION:	2133 HRS
DRILL:	SANDVIK - HYDRASTAR H200
TIRE SIZE:	12.00 - 20 - RIM - 12 BOLT - 5" INSET - 14.5" CENTER
OPEN CANOPY:	
ROPS/FOPS:	YES -
OPEN CANOPY CONDITION:	GOOD
VOLTAGE:	575VAC / 3 PHASE / 60 HZ
POWER PACK HRS.	6404 HRS



YZC EQUIPMENT INSPECTION REPORT

UNIT YZ-402 DESCRIPTION MACLEAN 928 BOLTER HOURS 1258DATE 06/07/16....

RUNNING INFORMATION
ENGINE STARTS EASILY AND RUNS GOOD
LOW IDLE 800 HIGH IDLE 2320
ENGINE OIL PRESSURE LOW IDLE 59 P.S.I.
TURBO BOOST 34.2 P.S.I.
TRANSMISSION PRESSURE 300 P.S.I.
CHARGING VOLTAGE 27.5 VOLTS
NO ENGINE FAULTS
BRAKE PRESSURES
-DRILL END ACCUMULATOR 2100 PSI -ENGINE END ACCUMULATOR 2100 PSI
-BRAKE APPLY 650 PSI -PARK BRAKE RELEASE ONLY SHOWS 10 PSI BUT BRAKES RELEASE
TRANSMISSION SHIFTS GOOD AND RUNS GOOD, TWO FORWARD AND TWO REVERSE GEARS
PASSES PARK BRAKE AND SERVICE BRAKE TESTS
ELECTRIC PANEL HOURS
-POWER PACK 6405 -DRILL IMPACT 2133
600 VOLT WORKS GOOD NO POWER KICK OUTS
GENERAL INFORMATION
COMPRESSOR WORKS
ALL FOUR TIRES 90% REMAINING LIFE RIMS AND WHEEL BOLTS GOOD
REAR AXLE MOUNT BOLTS TIGHT, OSCILLATION AXLE GOOD
DRIVE LINES, SLIP JOINTS, "U" JOINTS GOOD
ENGINE MOUNTS GOOD, TRANSMISSION MOUNTS GOOD, RADIATOR MOUNTS GOOD
RADIATOR AND AIR TO AIR COOLER GOOD NO LEAKS , HOSING IS GOOD
STEERING CYLINDERS GOOD NO LEAKS, PINS/BUSHINGS GOOD,STOPS GOOD
ARTICULATION IS GOOD, AUTO GREASER WORKS
FRONT AND REAR JACKS GOOD, NO LEAKS
SCISSOR LIFT CYLINDERS GOOD, NO LEAKS, SCISSOR ROLLERS GOOD,SCISSOR FRAMES GOOD, NO CRACKS
ALL OPERATOR DASH SWITCHES AND GAUGES WORK

600 VOLT DECK LIGHT WORKS, BATTERIES ARE FAIR CONDITION
DECK EXTENSION CYLINDERS GOOD NO LEAKS
DRILL AND SWELLEX FEED/RETURN CHAINS ARE GOOD, BOTH FEEDS WORK
DRILL WORKS, PERCUSSION WORKS ON DRILL AND SWELLEX
DRILL CROWD WORKS, BOOM CROWD WORKS , SIDE SHIFT WORKS, TILT FUNCTION WORKS
DRILL HYDRAULIC CENTRALIZER WORKS
600 VOLT WATER BOOST PUMP WORKS

COMPLETE.....

.....SIGNATURE:.....



YZC EQUIPMENT INSPECTION REPORT

UNIT YZ-402 DESCRIPTION MACLEAN 928 BOLTER HOURS 2500DATE 06/07/16....

FAILED INSPECTION INFORMATION
DECK SLIDES NEED ADJUSTMENT
DRILL FEED GUIDES NEED ADJUSTMENT
BOLT FEED GUIDES NEED ADJUSTMENT
DRILL CROWD GUIDES NEED ADJUSTMENT
BOOM CROWD GUIDES NEED ADJUSTMENT
DRILL LEAKING NEAR FRONT SADDLE MOUNT
REAR DRILL BUMPER NOT WORKING
ONLY ONE REAR LIGHT ON DIESEL
ONLY ONE TAIL LIGHT
SWELLEX PUMP LOOSE ON DECK BUT WORKS
600V CABLE GUIDE ROLLERS SIEZED
SEAT WORN OUT
STINGER BALL WORN OUT
RIGHT FRONT GUARD RAIL BENT AND INTERFEREING WITH ELECTRIC PANEL ON DECK
RDS NOT WORKING
DECK FALL OUT WINGS BENT AND DAMAGED
SCISSOR DECK RAILINGS AND SAFETY CHAINS COULD USE SOME MINOR REPAIRS
REAR DRIVING LIGHT GAURDS PUSHED IN
HYDRAULIC HOSING NEEDS SOME TIDYING UP

COMPLETE.....

.....SIGNATURE:.....



YZ403	
MAKE:	MACLEAN
MODEL:	MEM - 928
YEAR:	
SERIAL NUMBER:	928-375
UNIT HOURS:	1150 HRS
FIRE SUPPRESSION:	YES - ANSUL
ENGINE MAKE:	MERCEDES - BENZ
ENGINE MODEL	OM904LA
TRANSMISSION MAKE:	
TRANSMISSION MODEL:	
CONVERTER MAKE:	
CONVERTER MODEL:	
BRAKES MAKE:	
BRAKES TYPE - SERVICE:	
BRAKES TYPE - PARKING - EMERGENCY:	
AXLES MAKE:	
AXLES MODEL:	
PERCUSSION:	2057 HRS
DRILL:	SANDVIK - HYDRASTAR H200
TIRE SIZE:	12.00 - 20 - RIM - 12 BOLT - 5" INSET - 14.5" CENTER
OPEN CANOPY:	
ROPS/FOPS:	YES -
OPEN CANOPY CONDITION:	GOOD
VOLTAGE:	575VAC / 3 PHASE / 60 HZ
POWER PACK HRS	5179 HRS



YZC EQUIPMENT INSPECTION REPORT

UNIT YZ-403 DESCRIPTION MACLEAN 928 BOLTER HOURS 1153DATE 12/07/16....

RUNNING INFORMATION
ENGINE STARTS EASILY AND RUNS GOOD
LOW IDLE 800 HIGH IDLE 2340
ENGINE OIL PRESSURE LOW IDLE 62 P.S.I.
TURBO BOOST 33.3 P.S.I.
TRANSMISSION PRESSURE 300 P.S.I.
CHARGING VOLTAGE 27.6 VOLTS
NO ENGINE FAULTS
BRAKE PRESSURES
-DRILL END ACCUMULATOR 2100 PSI -ENGINE END ACCUMULATOR 2100 PSI
-BRAKE APPLY 650 PSI -PARK BRAKE RELEASE 640 PSI
TRANSMISSION SHIFTS GOOD AND RUNS GOOD, TWO FORWARD AND TWO REVERSE GEARS
PASSES PARK BRAKE AND SERVICE BRAKE TESTS
ELECTRIC PANEL HOURS
-POWER PACK 5179 -DRILL IMPACT 2057
600 VOLT WORKS GOOD NO POWER KICK OUTS
GENERAL INFORMATION
COMPRESSOR WORKS
ALL FOUR TIRES GOOD, RIMS AND WHEEL BOLTS GOOD
REAR AXLE MOUNT BOLTS TIGHT, OSCILLATION AXLE GOOD
DRIVE LINES, SLIP JOINTS, "U" JOINTS GOOD
ENGINE MOUNTS GOOD, TRANSMISSION MOUNTS GOOD, RADIATOR MOUNTS GOOD
RADIATOR AND AIR TO AIR COOLER GOOD NO LEAKS , HOSING IS GOOD
ARTICULATION IS GOOD, AUTO GREASER WORKS
FRONT AND REAR JACKS GOOD, NO LEAKS
SCISSOR LIFT CYLINDERS GOOD, NO LEAKS, SCISSOR ROLLERS GOOD,SCISSOR FRAMES GOOD, NO CRACKS
ALL OPERATOR DASH SWITCHES AND GAUGES WORK
600 VOLT DECK LIGHT WORKS, BATTERIES ARE FAIR CONDITION

DECK EXTENSION CYLINDERS GOOD NO LEAKS
DRILL AND SWELLEX FEED/RETURN CHAINS ARE GOOD, BOTH FEEDS WORK
DRILL WORKS, PERCUSSION WORKS ON DRILL AND SWELLEX
DRILL CROWD WORKS, BOOM CROWD WORKS , SIDE SHIFT WORKS, TILT FUNCTION WORKS
DRILL HYDRAULIC CENTRALIZER WORKS
600 VOLT WATER BOOST PUMP WORKS

COMPLETE.....

.....SIGNATURE:.....



YZC EQUIPMENT INSPECTION REPORT

UNIT YZ-403..... DESCRIPTION MACLEAN 928 BOLTER HOURS 1153 .DATE 12/07/16....

FAILED INSPECTION INFORMATION
HYDRAULIC BRAKES ARE BLEEDING INTO REAR DIFFERENTIAL
LADDERS TO DECK ARE BENT
LH TAIL LIGHT NEEDS REPAIR
MISSING ONE WHEEL CHOCK HOLDER
SEAT IS NO GOOD FALLING APART
600 VOLT PANEL PLASTIC GUARD NEEDS REPAIRS
BOLTING DRIFTER LEAKING AT FRONT HEAD
FOOT THROTTLE STICKS
NO POWER TO RDS PANEL
BOTH STEERING CYLINDERS LEAK
PENDANT CORD STRAIN RELIEF NEEDS REPAIR
STINGER PAD WORN OUT
STINGER BALL WORN OUT
SCISSOR DECK RAILINGS AND SAFETY CHAINS COULD USE SOME MINOR REPAIRS
PLASTIC 600 VOLT PANEL CURTAIN PROTECTOR POOR CONDITION
HYDRAULIC HOSEING NEEDS SOME TIDYING UP

COMPLETE.....

.....SIGNATURE:.....