



YZ601

MAKE:	INDUSTRIAL FABRICATION
MODEL:	E SERIES LOADER 4400 MC100E
YEAR:	
SERIAL NUMBER:	IFI1006184
UNIT HOURS:	10,913
FIRE SUPPRESSION:	YES - ANSUL
ENGINE MAKE:	IVECO
ENGINE MODEL	N45
TRANSMISSION MAKE:	
TRANSMISSION MODEL:	
CONVERTER MAKE:	
CONVERTER MODEL:	
BRAKES MAKE:	
BRAKES TYPE - SERVICE:	
BRAKES TYPE - PARKING - EMERGENCY:	
AXLES MODEL - FRONT:	CARRARO
AXLES MODEL - REAR :	
TIRE SIZE - FRONT:	14 X 17.5
TIRE SIZE - REAR:	19.5 X 24 10 PLY
OPEN CANOPY:	
ROPS:	
FOPS:	YES
OPEN CANOPY CONDITION:	GOOD
FOPS:	YES
OPEN CANOPY CONDITION:	GOOD



# YZC EQUIPMENT INSPECTION REPORT

UNIT YZ-601..... DESCRIPTION MINECAT HOURS 952 ....DATE 03/07/16....

RUNNING INFORMATION
ENGINE STARTS EASILY AND RUNS GOOD
CHARGING VOLTAGE 27.7 VOLTS
TRANSMISSION SHIFTS GOOD AND RUNS GOOD, TWO FORWARD AND TWO REVERSE GEARS
PASSES PARK BRAKE AND SERVICE BRAKE TESTS
STEERING WHEEL TILT WORKS
GENERAL INFORMATION
THROTTLE LOCK WORKS
HOSE REELS WORK
OIL DISPENSING VALVEING GOOD
ALL FOUR TIRES GOOD, RIMS AND WHEEL BOLTS GOOD
REAR AXLE MOUNT BOLTS TIGHT
ENGINE MOUNTS GOOD, TRANSMISSION MOUNTS GOOD, RADIATOR MOUNTS GOOD
RADIATOR GOOD NO LEAKS , HOSING IS GOOD
STEERING LINKAGE GOOD , KNUCKLES GOOD,STOPS GOOD
AUTO GREASER WORKS
BOOM CONTROLS WORK

COMPLETE.....

.....SIGNATURE:.....



# YZC EQUIPMENT INSPECTION REPORT

UNIT YZ-601 ..... DESCRIPTION MINECAT HOURS 952....DATE 03/07/16....

FAILED INSPECTION INFORMATION
Engine oil pressure gauge broken
Fuel gauge broken
Tachometer does not work
FNR switch has no stops but works
Seat worn out
Seat belt restraint does not catch
Front left head light not working
Passenger seat ripped
Passenger seat belt does not latch
Boom quick attach bent
Front left fender bent up
Engine valve covers have minor leaks
Exhaust leak at scrubber inlet
Right rear wheel seal leaking
Left tilt cylinder has minor seeping
ROPS missing two bolts

COMPLETE.....

.....SIGNATURE:.....